

Remark: Availability based on prior sales

	Description	P/N	QTY	PCS
WALSIN	RF 0201 0.3P/25V ±0.1PF NPO	RF03N0R3B250	465.000	PCS
WALSIN	RF 0603 0.3P/50V ±0.1PF NPO	RF18N0R3B500	1.100.000	PCS
WALSIN	RF 0201 0.4P/25V ±0.1PF NPO	RF03N0R4B250	225.000	PCS
WALSIN	RF 0402 0.4P/50V ±0.1PF NPO	RF15N0R4B500	250.000	PCS
WALSIN	CHIP 0603 0.56P/50V ±0.25P NP	0603NR56C500	116.000	PCS
WALSIN	CHIP 0402 0.56P/50V ±0.25P NP	0402NR56C500	560.000	PCS
WALSIN	RF 0201 0.5P/25V ±0.1PF NPO	RF03N0R5B250	255.000	PCS
WALSIN	CHIP 0603 0.5P/50V ±0.1PF NP	0603N0R5B500	932.000	PCS
WALSIN	CHIP 0402 0.5P/50V ±0.1PF NPO	0402N0R5B500	140.000	PCS
WALSIN	CHIP 0805 0.5P/50V ±0.25PF NP	0805N0R5C500	224.000	PCS
WALSIN	RF 0201 0.6P/25V ±0.1PF NPO	RF03N0R6B250	570.000	PCS
WALSIN	RF 0402 0.6P/50V ±0.1PF NPO	RF15N0R6B500	300.000	PCS
WALSIN	CHIP 0603 0.75P/50V ±0.25 NPO	0603NR75C500	444.000	PCS
WALSIN	RF 0402 0.7P/50V ±0.1PF NPO	RF15N0R7B500	250.000	PCS
WALSIN	RF 0201 0.8P/25V ±0.1PF NPO	RF03N0R8B250	525.000	PCS
WALSIN	RF 0402 0.8P/50V ±0.1PF NPO	RF15N0R8B500	1.110.000	PCS
WALSIN	RF 0201 0.8P/50V ±0.25PF NPO	RF03N0R8C500	210.000	PCS
WALSIN	CHIP 0603 10P/50V ±0.25PF NPO	0603N100C500	176.000	PCS
WALSIN	CHIP 0201 10P/25V ±2% NPO	0201N100G250	150.000	PCS
WALSIN	CHIP 0603 10P/50V ±2% NPO	0603N100G500	156.000	PCS
WALSIN	CHIP 0603 10P/100V ±5% NPO	0603N100J101	120.000	PCS
WALSIN	CHIP 1206 10P/100V ±5% NPO	1206N100J101	420.000	PCS
WALSIN	CHIP 0402 10P/25V ±5% NPO	0402N100J250	470.000	PCS
WALSIN	CHIP 0201 10P/25V ±5% NPO	0201N100J250	2.145.000	PCS
WALSIN	RF 0201 10P/25V ±5% NPO	RF03N100J250	840.000	PCS
WALSIN	CHIP 0603 10P/50V ±5% NPO	0603N100J500	1.072.000	PCS
WALSIN	HH 0603 10P/50V ±5% NPO	HH18N100J500	408.000	PCS
WALSIN	CHIP 0402 10P/50V ±5% NPO	0402N100J500	5.246.000	PCS
WALSIN	CHIP 0201 10P/50V ±5% NPO	0201N100J500	6.300.000	PCS
WALSIN	RF 0201 10P/50V ±5% NPO	RF03N100J500	5.580.000	PCS
WALSIN	CHIP 0603 100P/50V ±1% NPO	0603N101F500	308.000	PCS
WALSIN	CHIP 1206 100P/100V ±5% NPO	1206N101J101	472.000	PCS
WALSIN	CHIP 0603 100P/10V ±5% NPO	0603N101J100	536.000	PCS
WALSIN	CHIP 1206 100P/1KV ±5% NPO	1206N101J102	354.000	PCS
WALSIN	CHIP 0201 100P/25V ±5% NPO	0201N101J250	1.905.000	PCS
WALSIN	CHIP 1206 100P/500V ±5% NPO	1206N101J501	104.000	PCS
WALSIN	CHIP 0603 100P/50V ±5% NPO	0603N101J500	168.000	PCS
WALSIN	CHIP 0805 100P/50V ±5% NPO	0805N101J500	164.000	PCS
WALSIN	CHIP 1206 100P/50V ±5% NPO	1206N101J500	1.964.000	PCS
WALSIN	CHIP 0402 100P/50V ±5% NPO	0402N101J500	13.850.000	PCS
WALSIN	CHIP 0201 100P/50V ±5% NPO	0201N101J500	4.920.000	PCS
WALSIN	CHIP 0603 100P/100V ±10% X7R	0603B101K101	200.000	PCS
WALSIN	CHIP 0201 100P/25V ±10% X7R	0201B101K250	330.000	PCS
WALSIN	CHIP 0603 100P/50V K NPO	0603N101K500	1.420.000	PCS
WALSIN	CHIP 0603 100P/50V ±10% X7R	0603B101K500	800.000	PCS
WALSIN	CHIP 0603 102P/50V ±1% NPO	0603N102F500	312.000	PCS
WALSIN	CHIP 0402 102P/50V ±1% NPO	0402N102F500	380.000	PCS
WALSIN	CHIP 0805 102P/50V ±2% NPO	0805N102G500	228.000	PCS
WALSIN	CHIP 0402 102P/50V ±2% NPO	0402N102G500	170.000	PCS

WALSIN	CHIP 0603 102P/100V \pm 5% NPO	0603N102J101	140.000	PCS
WALSIN	CHIP 0603 102P/25V \pm 5% NPO	0603N102J250	984.000	PCS
WALSIN	CHIP 0603 102P/50V \pm 5% X7R	0603B102J500	400.000	PCS
WALSIN	CHIP 0805 102P/50V \pm 5% X7R	0805B102J500	176.000	PCS
WALSIN	CHIP 0402 102P/50V \pm 5% X7R	0402B102J500	1.570.000	PCS
WALSIN	CHIP 0603 102P/100V \pm 10% X7R	0603B102K101	2.300.000	PCS
WALSIN	CHIP 0805 102P/100V \pm 10% X7R	0805B102K101	1.672.000	PCS
WALSIN	CHIP 1206 102P/100V \pm 10% X7R	1206B102K101	104.000	PCS
WALSIN	CHIP 0402 102P/100V \pm 10% X7R	0402B102K101	1.080.000	PCS
WALSIN	CHIP 0201 102P/16V \pm 10% X7R	0201B102K160	1.080.000	PCS
WALSIN	CHIP 0805 102P/1KV \pm 10% X7R	0805B102K102	288.000	PCS
WALSIN	CHIP 0805 102P/250V \pm 10% X7R	0805B102K251	208.000	PCS
WALSIN	CHIP 0201 102P/25V \pm 10% X7R	0201B102K250	11.475.000	PCS
WALSIN	1206 102P/2KV K X7R T:1.25mm	1206B102K202	7.038.000	PCS
WALSIN	1808 102PF/2KV K X7R T:1.25	1808B102K202	228.000	PCS
WALSIN	CHIP 0805 102P/500V \pm 10% X7R	0805B102K501	320.000	PCS
WALSIN	CHIP 0603 102P/50V \pm 10% X7R	0603B102K500	12.580.000	PCS
WALSIN	CHIP 0805 102P/50V \pm 10% X7R	0805B102K500	6.180.000	PCS
WALSIN	CHIP 1206 102P/50V \pm 10% X7R	1206B102K500	320.000	PCS
WALSIN	CHIP 0402 102P/50V \pm 10% X7R	0402B102K500	41.055.000	PCS
WALSIN	CHIP 0402 102P/50V \pm 10% X7R	MT15B102K500	110.000	PCS
WALSIN	CHIP 0402 102P/50V \pm 10% X7R		930.000	PCS
WALSIN	CHIP 0201 102P/50V \pm 10% X7R	0201B102K500	1.350.000	PCS
WALSIN	CHIP 1206 102P/630V \pm 10% X7R	1206B102K631	306.000	PCS
WALSIN	CHIP 0402 103P/16V \pm 5% X7R	0402B103J160	1.020.000	PCS
WALSIN	CHIP 0402 103P/25V \pm 5% X7R	0402B103J250	160.000	PCS
WALSIN	CHIP 0603 103P/100V \pm 10% X7R	0603B103K101	1.480.000	PCS
WALSIN	CHIP 0805 103P/100V \pm 10% X7R	0805B103K101	381.000	PCS
WALSIN	CHIP 1206 103P/100V \pm 10% X7R	1206B103K101	1.160.000	PCS
WALSIN	CHIP 0201 103P/10V \pm 10% X5R	0201X103K100	285.000	PCS
WALSIN	CHIP 0402 103P/10V \pm 10% X7R	0402B103K100	770.000	PCS
WALSIN	CHIP 0201 103P/10V \pm 10% X7R	0201B103K100	4.750.000	PCS
WALSIN	CHIP 0402 103P/16V \pm 10% X7R	0402B103K160	130.000	PCS
WALSIN	1206 103P/1KV K X7R T:1.25mm	1206B103K102 3K/R	423.000	PCS
WALSIN	CHIP 0805 103P/250V \pm 10% X7R	0805B103K251	132.000	PCS
WALSIN	CHIP 0603 103P/25V \pm 10% X7R	0603B103K250	524.000	PCS
WALSIN	CHIP 0402 103P/25V \pm 10% X7R	0402B103K250	880.000	PCS
WALSIN	CHIP 0603 103P/50V \pm 10% X7R	0603B103K500	19.446.000	PCS
WALSIN	CHIP 0603 103P/50V \pm 10% X7R車	MG18B103K500CT	120.000	PCS
WALSIN	CHIP 1206 103P/50V \pm 10% X7R	1206B103K500	540.000	PCS
WALSIN	CHIP 0402 103P/50V \pm 10% X7R	0402B103K500	41.786.000	PCS
WALSIN	CHIP 0402 103P/50V Z Y5V	0402F103Z500	200.000	PCS
WALSIN	CHIP 0805 104P/100V \pm 5% X7R	0805B104J101	174.000	PCS
WALSIN	CHIP 0402 104P/16V \pm 5% X7R		130.000	PCS
WALSIN	CHIP 0603 104P/25V \pm 5% X7R	0603B104J250	360.000	PCS
WALSIN	CHIP 0603 104P/50V \pm 5% X7R	0603B104J500	4.628.000	PCS
WALSIN	CHIP 0805 104P/100V \pm 10% X7R	0805B104K101	7.860.000	PCS
WALSIN	CHIP 1812 104P/100V \pm 10% X7R	1812B104K101	161.000	PCS
WALSIN	CHIP 0402 104P/10V \pm 10% X7R	0402B104K100	4.150.000	PCS
WALSIN	CHIP 0201 104P/16V \pm 10% X5R	0201X104K160	14.910.000	PCS
WALSIN	CHIP 0603 104P/16V \pm 10% X7R	0603B104K160	4.080.000	PCS
WALSIN	CHIP 0402 104P/16V \pm 10% X7R	0402B104K160	15.210.000	PCS
WALSIN	CHIP 1206 104P/200V \pm 10% X7R	1206B104K201	208.000	PCS
WALSIN	1206 104P/250V \pm 10% X7R T:1.6	1206B104K251	602.000	PCS
WALSIN	CHIP 1210 104P/250V \pm 10% X7R	1210B104K251	466.000	PCS
WALSIN	CHIP 0201 104P/25V \pm 10% X5R	0201X104K250	2.310.000	PCS
WALSIN	CHIP 0603 104P/25V \pm 10% X7R	0603B104K250	216.000	PCS
WALSIN	CHIP 1812 104P/500V \pm 10% X7R	1812B104K501	134.000	PCS
WALSIN	CHIP 0402 104P/50V \pm 10% X5R	0402X104K500	1.930.000	PCS

WALSIN	0603 104P/50V ±10% X7R 車用	MT18B104K500	100.000	PCS
WALSIN	CHIP 0805 104P/50V ±10% X7R	0805B104K500	632.000	PCS
WALSIN	CHIP 0201 104P/6.3V ±10% X5R	0201X104K6R3	729.385.000	PCS
WALSIN	CHIP 0402 104P/16V ±20% Y5V	0402F104M160	460.000	PCS
WALSIN	CHIP 0603 104P/25V ±20% X7R	0603B104M250	1.888.000	PCS
WALSIN	CHIP 0402 104P/16V Z Y5V	0402F104Z160	1.380.000	PCS
WALSIN	CHIP 0603 104P/50V Z Y5V	0603F104Z500	19.020.000	PCS
WALSIN	CHIP 1206 105P/100V ±10% X7R	1206B105K101	174.000	PCS
WALSIN	CHIP 0603 105P/10V ±10% X5R	0603X105K100	748.000	PCS
WALSIN	CHIP 0402 105P/10V ±10% X5R	0402X105K100	160.000	PCS
WALSIN	CHIP 0603 105P/16V ±10% X5R	0603X105K160	1.424.000	PCS
WALSIN	CHIP 0402 105P/16V ±10% X5R	0402X105K160	1.670.000	PCS
WALSIN	CHIP 0603 105P/16V ±10% X7R	0603B105K160	25.852.000	PCS
WALSIN	CHIP 0402 105P/25V ±10% X5R	0402X105K250	120.000	PCS
WALSIN	CHIP 0603 105P/25V ±10% X7R	0603B105K250	2.204.000	PCS
WALSIN	CHIP 0603 105P/50V ±10% X5R	0603X105K500	404.000	PCS
WALSIN	CHIP 0805 105P/50V ±10% X5R	0805X105K500	285.000	PCS
WALSIN	CHIP 0603 105P/6.3V ±10% X5R	0603X105K6R3	212.000	PCS
WALSIN	CHIP 0402 105P/6.3V ±10% X5R	0402X105K6R3	2.170.000	PCS
WALSIN	CHIP 0201 105P/10V ±20% X5R	0201X105M100	180.000	PCS
WALSIN	CHIP 0603 105P/10V Z Y5V	0603F105Z100	312.000	PCS
WALSIN	CHIP 0603 105P/16V Z Y5V	0603F105Z160	344.000	PCS
WALSIN	CHIP 0603 106P/10V ±10% X5R	0603X106K100	112.000	PCS
WALSIN	CHIP 0805 106P/16V ±10% X5R	0805X106K160	280.000	PCS
WALSIN	CHIP 1206 106P/50V ±10% X5R	1206X106K500	124.000	PCS
WALSIN	CHIP 0603 106P/6V3 ±10% X5R	0603X106K6R3	512.000	PCS
WALSIN	CHIP 0805 106P/6V3 ±10% X5R	0805X106K6R3	969.000	PCS
WALSIN	CHIP 0805 106P/10V ±20% Y5V	0805F106M100	4.644.000	PCS
WALSIN	CHIP 1206 106P/25V ±20% X5R	1206X106M250	170.000	PCS
WALSIN	CHIP 0603 106P/6V3 ±20% X5R	0603X106M6R3	6.000.000	PCS
WALSIN	CHIP 0402 106P/6.3V ±20% X5R	0402X106M6R3	530.000	PCS
WALSIN	CHIP 0805 106P/10V Z Y5V	0805F106Z100	855.000	PCS
WALSIN	CHIP 1206 106P/10V Z Y5V	1206F106Z100	293.000	PCS
WALSIN	CHIP 1210 106P/16V Z Y5V	1210F106Z160	201.000	PCS
WALSIN	CHIP 0603 12P/50V ±1% NPO	0603N120F500	220.000	PCS
WALSIN	CHIP 0402 12P/50V ±1% NPO	0402N120F500	190.000	PCS
WALSIN	CHIP 0201 12P/50V ±1% NPO	0201N120F500	255.000	PCS
WALSIN	CHIP 0603 12P/50V ±2% NPO	0603N120G500	104.000	PCS
WALSIN	CHIP 0402 12P/50V ±2% NPO	0402N120G500	1.440.000	PCS
WALSIN	CHIP 0201 12P/50V ±2% NPO	0201N120G500	570.000	PCS
WALSIN	CHIP 0603 12P/50V ±5% NPO	0603N120J500	2.056.000	PCS
WALSIN	CHIP 0402 12P/50V ±5% NPO	0402N120J500	110.000	PCS
WALSIN	CHIP 0201 12P/50V ±5% NPO	0201N120J500	1.170.000	PCS
WALSIN	CHIP 0805 120P/50V ±2% NPO	0805N121G500	160.000	PCS
WALSIN	CHIP 0805 120P/250V ±5% NPO	0805N121J251	120.000	PCS
WALSIN	CHIP 0603 120P/50V ±5% NPO	0603N121J500	260.000	PCS
WALSIN	CHIP 0603 122P/50V ±10% X7R	0603B122K500	416.000	PCS
WALSIN	CHIP 0805 123P/100V ±10% X7R	0805B123K101	800.000	PCS
WALSIN	CHIP 0402 123P/16V ±10% X7R	0402B123K160	1.810.000	PCS
WALSIN	CHIP 2225 125P/250V ±10% X7R	MA2225XR-125K-251ER	148.000	PCS
WALSIN	CHIP 0603 13P/50V ±2% NPO	0603N130G500	136.000	PCS
WALSIN	CHIP 0603 15P/50V ±1% NPO	0603N150F500	444.000	PCS
WALSIN	CHIP 0603 15P/50V ±2% NPO	0603N150G500	232.000	PCS
WALSIN	CHIP 0603 15P/50V ±5% NPO	0603N150J500	1.812.000	PCS
WALSIN	HH 0603 15P/50V ±5% NPO	HH18N150J500	436.000	PCS
WALSIN	CHIP 0805 15P/50V 5% NPO	0805N150J500	180.000	PCS
WALSIN	CHIP 0402 15P/50V ±5% NPO	0402N150J500	870.000	PCS
WALSIN	CHIP 0201 15P/50V ±5% NPO	0201N150J500	2.760.000	PCS
WALSIN	CHIP 0603 150P/50V ±5% NPO	0603N151J500	308.000	PCS

WALSIN	CHIP 1206 150P/50V ±5% NPO	1206N151J500	108.000	PCS
WALSIN	CHIP 0402 150P/50V ±5% NPO	0402N151J500	370.000	PCS
WALSIN	CHIP 0603 150P/50V ±10% X7R	0603B151K500	168.000	PCS
WALSIN	CHIP 0805 152P/50V ±5% NPO	0805N152J500	100.000	PCS
WALSIN	CHIP 0402 152P/50V ±5% X7R	0402B152J500	100.000	PCS
WALSIN	CHIP 0603 152P/25V ±10% X7R	0603B152K250	228.000	PCS
WALSIN	CHIP 0603 152P/50V ±10% X7R	0603B152K500	184.000	PCS
WALSIN	CHIP 0402 153P/16V ±10% X7R	0402B153K160	1.010.000	PCS
WALSIN	CHIP 1206 153P/200V ±10% X7R	1206B153K201	102.000	PCS
WALSIN	CHIP 0805 153P/250V ±10% X7R	0805B153K251	300.000	PCS
WALSIN	CHIP 1206 153P/250V ±10% X7R	1206B153K251	540.000	PCS
WALSIN	CHIP 0402 153P/25V ±10% X7R	0402B153K250	140.000	PCS
WALSIN	CHIP 0603 154P/25V ±10% X7R	0603B154K250	124.000	PCS
WALSIN	CHIP 0805 154P/50V ±10% X7R	0805B154K500	129.000	PCS
WALSIN	CHIP 0603 16P/50V ±2% NPO	0603N160G500	164.000	PCS
WALSIN	CHIP 0402 18P/50V ±1% NPO	0402N180F500	320.000	PCS
WALSIN	CHIP 0603 18P/50V ±2% NPO	0603N180G500	176.000	PCS
WALSIN	CHIP 0201 18P/25V ±5% NPO	0201N180J250	165.000	PCS
WALSIN	CHIP 0603 18P/50V ±5% NPO	0603N180J500	1.820.000	PCS
WALSIN	CHIP 0201 18P/50V ±5% NPO	0201N180J500	5.820.000	PCS
WALSIN	CHIP 0603 180P/50V ±2% NPO	0603N181G500	120.000	PCS
WALSIN	CHIP 0603 180P/50V ±5% NPO	0603N181J500	532.000	PCS
WALSIN	CHIP 0402 180P/50V ±5% NPO	0402N181J500	940.000	PCS
WALSIN	CHIP 1206 182P/100V ±5% NPO	1206N182J101	136.000	PCS
WALSIN	CHIP 0805 182P/50V ±5% NPO	0805N182J500	124.000	PCS
WALSIN	CHIP 0603 182P/50V ±10% X7R	0603B182K500	144.000	PCS
WALSIN	CHIP 0603 183P/50V ±10% X7R	0603B183K500	388.000	PCS
WALSIN	RF 0402 1P/50V ±0.1PF NPO	RF15N1R0B500	180.000	PCS
WALSIN	CHIP 0603 1P/50V ±0.25PF NPO	0603N1R0C500	804.000	PCS
WALSIN	CHIP 0805 1P/50V ±0.25PF NPO	0805N1R0C500	140.000	PCS
WALSIN	RF 0201 1.2P/25V ±0.1PF NPO	RF03N1R2B250	540.000	PCS
WALSIN	CHIP 0603 1.2P/50V ±0.1PF NPO	0603N1R2B500	140.000	PCS
WALSIN	CHIP 0402 1.2P/50V ±0.1PF NP	0402N1R2B500	120.000	PCS
WALSIN	RF 0402 1.2P/50V ±0.1PF NPO	RF15N1R2B500	310.000	PCS
WALSIN	CHIP 0603 1.2P/50V ±0.25PF NP	0603N1R2C500	232.000	PCS
WALSIN	CHIP 0805 1.2P/50V ±0.25PF NP	0805N1R2C500	208.000	PCS
WALSIN	CHIP 0402 1.2P/50V ±0.25PF NP	0402N1R2C500	990.000	PCS
WALSIN	CHIP 0201 1.2P/50V ±0.25PF NP	0201N1R2C500	270.000	PCS
WALSIN	RF 0201 1.4P/25V ±0.1PF NPO	RF03N1R4B250	495.000	PCS
WALSIN	RF 0201 1.5P/25V ±0.1PF NPO	RF03N1R5B250	630.000	PCS
WALSIN	CHIP 0603 1.5P/50V ±0.1PF NPO	0603N1R5B500	124.000	PCS
WALSIN	CHIP 0402 1.5P/50V ±0.1PF NPO	0402N1R5B500	160.000	PCS
WALSIN	CHIP 0201 1.5P/50V ±0.1PF NPO	0201N1R5B500	660.000	PCS
WALSIN	CHIP 0805 1.5P/50V ±0.25PF NP	0805N1R5C500	260.000	PCS
WALSIN	CHIP 0402 1.5P/50V ±0.25PF NP	0402N1R5C500	350.000	PCS
WALSIN	RF 0201 1.8P/25V ±0.1PF NPO	RF03N1R8B250	285.000	PCS
WALSIN	RF 0402 1.8P/50V ±0.1PF NPO	RF15N1R8B500	240.000	PCS
WALSIN	CHIP 0805 1.8P/50V ±0.25PF NP	0805N1R8C500	124.000	PCS
WALSIN	CHIP 0402 1.8P/50V ±0.25PF NP	0402N1R8C500	110.000	PCS
WALSIN	CHIP 0201 1.8P/50V ±0.25PF NP	0201N1R8C500	750.000	PCS
WALSIN	CHIP 0603 20P/50V ±2% NPO	0603N200G500	240.000	PCS
WALSIN	CHIP 0603 20P/50V ±5% NPO	0603N200J500	1.388.000	PCS
WALSIN	CHIP 0402 20P/50V ±5% NPO	0402N200J500	1.790.000	PCS
WALSIN	CHIP 0201 20P/50V ±5% NPO	0201N200J500	150.000	PCS
WALSIN	CHIP 0603 200P/50V ±10% X7R	0603B201K500	760.000	PCS
WALSIN	CHIP 0402 202P/50V ±10% X7R	0402B202K500	200.000	PCS
WALSIN	CHIP 0201 22P/25V ±2% NPO	0201N220G250	180.000	PCS
WALSIN	1206 22P/1KV ±5% NPO T:1.25mm	1206N220J102	261.000	PCS
WALSIN	CHIP 0201 22P/25V ±5% NPO	0201N220J250	1.470.000	PCS

WALSIN	RF 0201 22P/25V ±5% NPO	RF03N220J250	600.000	PCS
WALSIN	CHIP 0603 22P/50V ±5% NPO	0603N220J500	768.000	PCS
WALSIN	CHIP 0805 22P/50V ±5% NPO	0805N220J500	136.000	PCS
WALSIN	CHIP 0201 22P/50V ±5% NPO	0201N220J500	645.000	PCS
WALSIN	CHIP 0603 220P/100V ±10% X7R	0603B221K101	224.000	PCS
WALSIN	CHIP 0201 220P/25V ±10% X7R	0201B221K250	180.000	PCS
WALSIN	CHIP 0402 220P/50V ±10% X7R	0402B221K500	650.000	PCS
WALSIN	CHIP 0603 222P/50V ±5% NPO	0603N222J500	2.936.000	PCS
WALSIN	CHIP 0805 222P/50V ±5% NPO	0805N222J500	224.000	PCS
WALSIN	CHIP 0201 222P/10V ±10% X5R	0201X222K100	180.000	PCS
WALSIN	CHIP 1206 222P/1KV ±10% X7R	1206B222K102	507.000	PCS
WALSIN	CHIP 0805 222P/250V ±10% X7R	0805B222K251	672.000	PCS
WALSIN	CHIP 0201 222P/25V ±10% X7R	0201B222K250	495.000	PCS
WALSIN	CHIP 0402 222P/50V ±10% X7R	0402B222K500	680.000	PCS
WALSIN	CHIP 0402 223P/10V ±10% X7R	0402B223K100	180.000	PCS
WALSIN	CHIP 0805 223P/50V ±10% X7R	0805B223K500	552.000	PCS
WALSIN	CHIP 0201 223P/6V3 ±10% X5R	0201X223K6R3	1.080.000	PCS
WALSIN	CHIP 0603 223P/25V ±20% X7R	0603B223M250	148.000	PCS
WALSIN	CHIP 0402 224P/16V ±10% X5R	0402X224K160	590.000	PCS
WALSIN	CHIP 0603 224P/16V ±10% X7R	0603B224K160	680.000	PCS
WALSIN	CHIP 0402 224P/16V ±10% X7R	0402B224K160	4.920.000	PCS
WALSIN	CHIP 0603 224P/25V ±10% X7R	0603B224K250	2.104.000	PCS
WALSIN	CHIP 0603 224P/50V ±10% X7R	0603B224K500	380.000	PCS
WALSIN	CHIP 1206 224P/50V ±10% X7R	1206B224K500	126.000	PCS
WALSIN	CHIP 0402 224P/6.3V ±10% X5R	0402X224K6R3	1.800.000	PCS
WALSIN	CHIP 0201 224P/6.3V ±10% X5R	0201X224K6R3	6.480.000	PCS
WALSIN	CHIP 0402 224P/10V Z Y5V	0402F224Z100	730.000	PCS
WALSIN	CHIP 0603 224P/16V Z Y5V	0603F224Z160	236.000	PCS
WALSIN	CHIP 0603 224P/25V Z Y5V	0603F224Z250	176.000	PCS
WALSIN	CHIP 0603 224P/50V Z Y5V	0603F224Z500	120.000	PCS
WALSIN	CHIP 1812 225P/100V ±10% X7R	1812B225K101	134.500	PCS
WALSIN	CHIP 1210 225P/100V ±10% X7R	1210B225K101	329.000	PCS
WALSIN	CHIP 0603 225P/10V ±10% X5R	0603X225K100	232.000	PCS
WALSIN	CHIP 0805 225/10V K X5R 13"	0805X225K100 13"	100.000	PCS
WALSIN	CHIP 0603 225P/10V ±10% X7R	0603B225K100	224.000	PCS
WALSIN	CHIP 0603 225P/16V ±10% X5R	0603X225K160	1.888.000	PCS
WALSIN	CHIP 1206 225P/50V ±10% X7R	1206B225K500	172.000	PCS
WALSIN	CHIP 0603 225P/6V3 ±10% X5R	0603X225K6R3	672.000	PCS
WALSIN	CHIP 0402 225P/6.3V ±10% X5R	0402X225K6R3	3.670.000	PCS
WALSIN	CHIP 0402 225P/6.3V ±20% X5R	0402X225M6R3	1.550.000	PCS
WALSIN	CHIP 0805 226P/6.3V ±10% X5R	0805X226K6R3	354.000	PCS
WALSIN	CHIP 1206 226P/6.3V ±10% X5R	1206X226K6R3	192.000	PCS
WALSIN	CHIP 1210 226P/16V ±20% X5R	1210X226M160	123.000	PCS
WALSIN	CHIP 1210 226P/16V ±20% X7R	1210B226M160	107.000	PCS
WALSIN	CHIP 0603 226P/6.3V ±20% X5R	0603X226M6R3	4.060.000	PCS
WALSIN	CHIP 0805 226P/6.3V ±20% X5R	0805X226M6R3	720.000	PCS
WALSIN	CHIP 1206 226P/10V Z Y5V	1206F226Z100	118.000	PCS
WALSIN	CHIP 0603 24P/50V ±2% NPO	0603N240G500	120.000	PCS
WALSIN	CHIP 0402 24P/50V ±5% NPO	0402N240J500	730.000	PCS
WALSIN	CHIP 0603 27P/50V ±1% NPO	0603N270F500	100.000	PCS
WALSIN	CHIP 0402 27P/50V ±1% NPO	0402N270F500	250.000	PCS
WALSIN	CHIP 0603 27P/50V ±5% NPO	0603N270J500	1.616.000	PCS
WALSIN	CHIP 0805 27P/50V ±5% NPO	0805N270J500	552.000	PCS
WALSIN	CHIP 0201 27P/50V ±5% NPO	0201N270J500	570.000	PCS
WALSIN	CHIP 0402 270P/50V ±2% NPO	0402N271G500	100.000	PCS
WALSIN	CHIP 0402 270P/16V ±5% NPO	0402N271J160	140.000	PCS
WALSIN	CHIP 0603 270P/50V ±5% NPO	0603N271J500	312.000	PCS
WALSIN	CHIP 0603 270P/50V ±10% X7R	0603B271K500	324.000	PCS
WALSIN	CHIP 0805 270P/50V ±10% X7R	0805B271K500	200.000	PCS

WALSIN	CHIP 0603 272P/50V ±5% NPO	0603N272J500	344.000	PCS
WALSIN	CHIP 0805 272P/100V ±10% X7R	0805B272K101	100.000	PCS
WALSIN	CHIP 0201 2P/25V ±0.1PF NPO	0201N2R0B250	1.545.000	PCS
WALSIN	RF 0201 2P/25V ±0.1PF NPO	RF03N2R0B250	315.000	PCS
WALSIN	RF 0201 2.2P/25V ±0.1PF NPO	RF03N2R2B250	195.000	PCS
WALSIN	CHIP 0201 2.2P/50V ±0.1PF NPO	0201N2R2B500	150.000	PCS
WALSIN	CHIP 0603 2.2P/50V ±0.25PF NP	0603N2R2C500	216.000	PCS
WALSIN	CHIP 0402 2.2P/50V ±0.25PF NP	0402N2R2C500	800.000	PCS
WALSIN	CHIP 0402 2.4P/50V ±0.1PF NPO	0402N2R4B500	1.120.000	PCS
WALSIN	CHIP 0402 2.7P/50V ±0.1PF NPO	0402N2R7B500	460.000	PCS
WALSIN	CHIP 0402 2.7P/50V ±0.25PF NP	0402N2R7C500	170.000	PCS
WALSIN	CHIP 0201 2.7P/50V ±0.25PF NP	0201N2R7C500	1.575.000	PCS
WALSIN	CHIP 0603 30P/50V ±5% NPO	0603N300J500	352.000	PCS
WALSIN	CHIP 0402 30P/50V ±5% NPO	0402N300J500	1.240.000	PCS
WALSIN	CHIP 0603 33P/50V ±2% NPO	0603N330G500	200.000	PCS
WALSIN	CHIP 0201 33P/25V ±5% NPO	0201N330J250	150.000	PCS
WALSIN	CHIP 1808 33P/3KV ±5% NPO	1808N330J302	110.000	PCS
WALSIN	CHIP 0603 33P/50V ±5% NPO	0603N330J500	1.016.000	PCS
WALSIN	CHIP 0805 33P/50V ±5% NPO	0805N330J500	104.000	PCS
WALSIN	CHIP 0603 330P/50V ±5% NPO	0603N331J500	916.000	PCS
WALSIN	CHIP 0805 330P/50V ±5% NPO	0805N331J500	1.112.000	PCS
WALSIN	CHIP 1206 330P/50V ±5% NPO	1206N331J500	128.000	PCS
WALSIN	CHIP 0402 330P/50V ±5% NPO	0402N331J500	4.890.000	PCS
WALSIN	CHIP 0805 330P/50V ±10% X7R	0805B331K500	764.000	PCS
WALSIN	CHIP 0201 330P/50V ±10% X7R	0201B331K500	300.000	PCS
WALSIN	CHIP 0603 332P/50V ±5% NPO	0603N332J500	120.000	PCS
WALSIN	CHIP 0603 332P/50V ±5% X7R	0603B332J500	140.000	PCS
WALSIN	CHIP 0201 332P/16V ±10% X7R	0201B332K160	405.000	PCS
WALSIN	CHIP 0603 332P/50V ±10% X7R	0603B332K500	1.372.000	PCS
WALSIN	CHIP 0603 333P/50V ±10% X7R	0603B333K500	1.052.000	PCS
WALSIN	CHIP 0805 333P/50V ±10% X7R	0805B333K500	596.000	PCS
WALSIN	CHIP 0402 333P/50V ±10% X7R	0402B333K500CT	370.000	PCS
WALSIN	CHIP 1206 334P/100V ±10% X7R	1206B334K101	100.000	PCS
WALSIN	CHIP 0603 334P/16V ±10% X7R	0603B334K160	936.000	PCS
WALSIN	CHIP 0603 334P/25V ±10% X5R	0603X334K250	180.000	PCS
WALSIN	CHIP 0603 334P/25V ±10% X7R	0603B334K250	316.000	PCS
WALSIN	CHIP 0603 334P/50V ±10% X7R	0603B334K500	264.000	PCS
WALSIN	CHIP 0402 334P/6.3V ±10% X5R	0402X334K6R3	750.000	PCS
WALSIN	CHIP 0402 334P/10V Z Y5V	0402F334Z100	180.000	PCS
WALSIN	CHIP 0603 334P/16V Z Y5V	0603F334Z160	484.000	PCS
WALSIN	CHIP 0603 334P/25V Z Y5V	0603F334Z250	116.000	PCS
WALSIN	CHIP 0603 335P/6V3 ±10% X5R	0603X335K6R3	136.000	PCS
WALSIN	CHIP 0603 36P/50V ±5% NPO	0603N360J500	412.000	PCS
WALSIN	CHIP 0603 360P/50V ±2% NPO	0603N361G500	128.000	PCS
WALSIN	CHIP 0603 39P/50V ±5% NPO	0603N390J500	1.892.000	PCS
WALSIN	CHIP 0805 39P/50V ±5% NPO	0805N390J500	384.000	PCS
WALSIN	CHIP 0201 39P/50V ±5% NPO	0201N390J500	315.000	PCS
WALSIN	CHIP 0603 390P/50V ±5% NPO	0603N391J500	220.000	PCS
WALSIN	CHIP 0402 390P/50V ±5% NPO	0402N391J500	720.000	PCS
WALSIN	CHIP 1206 390P/1KV ±10% X7R	FV31X391K102ECG	156.000	PCS
WALSIN	CHIP 0402 390P/50V ±10% X7R	0402B391K500	4.310.000	PCS
WALSIN	CHIP 0603 392P/50V ±5% X7R	0603B392J500	240.000	PCS
WALSIN	CHIP 0603 392P/50V ±10% X7R	0603B392K500	260.000	PCS
WALSIN	CHIP 0402 392P/50V ±10% X7R	0402B392K500	660.000	PCS
WALSIN	CHIP 0402 393P/16V ±10% X7R	0402B393K160	130.000	PCS
WALSIN	CHIP 0603 394P/25V ±10% X7R	0603B394K250	180.000	PCS
WALSIN	CHIP 0603 3P/50V ±0.25PF NPO	0603N3R0C500	220.000	PCS
WALSIN	RF 0201 3.3P/25V ±0.1PF NPO	RF03N3R3B250	570.000	PCS
WALSIN	RF 0402 3.3P/50V ±0.1PF NPO	RF15N3R3B500	270.000	PCS

WALSIN	CHIP 0201 3.3P/50V \pm 0.1PF NPO	0201N3R3B500	120.000	PCS
WALSIN	CHIP 0603 3.3P/50V \pm 0.25PF NP	0603N3R3C500	540.000	PCS
WALSIN	CHIP 0805 3.3P/50V \pm 0.25PF NP	0805N3R3C500	140.000	PCS
WALSIN	CHIP 0402 3.3P/50V \pm 0.25PF NP	0402N3R3C500	200.000	PCS
WALSIN	CHIP 0402 3.6P/50V \pm 0.25PF NP	0402N3R6C500	120.000	PCS
WALSIN	RF 0402 3.6P/50V \pm 0.25PF NP	RF15N3R6C500	160.000	PCS
WALSIN	CHIP 0603 3.9P/50V \pm 0.1PF NPO	0603N3R9B500	156.000	PCS
WALSIN	CHIP 0201 3.9P/50V \pm 0.1PF NPO	0201N3R9B500CT	180.000	PCS
WALSIN	CHIP 0805 3.9P/50V \pm 0.25PF NP	0805N3R9C500	100.000	PCS
WALSIN	CHIP 0402 3.9P/50V \pm 0.25PF NP	0402N3R9C500	780.000	PCS
WALSIN	CHIP 0201 3.9P/50V \pm 0.25PF NP	0201N3R9C500	180.000	PCS
WALSIN	CHIP 0603 43P/50V \pm 5% NPO	0603N430J500	396.000	PCS
WALSIN	CHIP 0603 47P/50V \pm 2% NPO	0603N470G500	140.000	PCS
WALSIN	CHIP 0805 47P/100V \pm 5% NPO	0805N470J101	120.000	PCS
WALSIN	CHIP 0603 47P/50V \pm 5% NPO	0603N470J500	316.000	PCS
WALSIN	CHIP 0402 47P/50V \pm 5% NPO	0402N470J500	1.900.000	PCS
WALSIN	CHIP 0402 470P/50V \pm 2% NPO	0402N471G500	120.000	PCS
WALSIN	CHIP 0603 470P/100V \pm 5% NPO	0603N471J101	728.000	PCS
WALSIN	CHIP 1206 470P/1KV \pm 5% NPO	1206N471J102	220.000	PCS
WALSIN	CHIP 0603 470P/50V \pm 5% NPO	0603N471J500	2.746.000	PCS
WALSIN	CHIP 0402 470P/50V \pm 5% NPO	0402N471J500	2.800.000	PCS
WALSIN	CHIP 1206 470P/1KV \pm 10% X7R	1206B471K102	105.000	PCS
WALSIN	CHIP 0201 470P/25V \pm 10% X7R	0201B471K250	435.000	PCS
WALSIN	CHIP 0805 470P/500V \pm 10% X7R	0805B471K501	152.000	PCS
WALSIN	CHIP 0402 470P/50V \pm 10% X7R	0402B471K500	4.950.000	PCS
WALSIN	CHIP 0603 472P/50V \pm 5% NPO	0603N472J500	204.000	PCS
WALSIN	CHIP 0603 472P/100V \pm 10% X7R	0603B472K101	116.000	PCS
WALSIN	CHIP 0201 472P/16V \pm 10% X7R	0201B472K160	165.000	PCS
WALSIN	CHIP 0805 472P/250V \pm 10% X7R	0805B472K251	200.000	PCS
WALSIN	CHIP 0402 472P/25V \pm 10% X7R	0402B472K250	120.000	PCS
WALSIN	CHIP 1210 472P/2KV \pm 10% X7R	1210B472K202	266.000	PCS
WALSIN	CHIP 0603 472P/50V \pm 10% X7R	0603B472K500	2.244.000	PCS
WALSIN	CHIP 0402 472P/50V \pm 10% X7R	0402B472K500	100.000	PCS
WALSIN	CHIP 1206 472P/630V \pm 10% X7R	1206B472K631	1.473.000	PCS
WALSIN	CHIP 0201 473P/10V \pm 10% X5R	0201X473K100	345.000	PCS
WALSIN	CHIP 0402 473P/16V \pm 10% X7R	0402B473K160	220.000	PCS
WALSIN	CHIP 1206 473P/250V \pm 10% X7R	1206B473K251	232.000	PCS
WALSIN	CHIP 0402 473P/25V \pm 10% X7R	0402B473K250	640.000	PCS
WALSIN	CHIP 0603 473P/50V \pm 10% X7R	0603B473K500	596.000	PCS
WALSIN	CHIP 0201 473P/6.3V \pm 10% X5R	0201X473K6R3	150.000	PCS
WALSIN	CHIP 0603 474P/10V \pm 10% X5R	0603X474K100	1.184.000	PCS
WALSIN	CHIP 0603 474P/10V \pm 10% X7R	0603B474K100	216.000	PCS
WALSIN	CHIP 0603 474P/16V \pm 10% X7R	0603B474K160	5.108.000	PCS
WALSIN	CHIP 1210 474P/250V \pm 10% X7R	1210B474K251	319.000	PCS
WALSIN	CHIP 0603 474P/25V \pm 10% X5R	0603X474K250	120.000	PCS
WALSIN	CHIP 0603 474P/25V \pm 10% X7R	0603B474K250	188.000	PCS
WALSIN	CHIP 0603 474P/50V \pm 10% X5R	0603X474K500	188.000	PCS
WALSIN	CHIP 0402 474P/50V \pm 10% X5R	0402X474K500	370.000	PCS
WALSIN	CHIP 0805 474P/50V \pm 10% X7R	0805B474K500	428.000	PCS
WALSIN	CHIP 0402 474P/6V3 \pm 10% X5R	0402X474K6R3	900.000	PCS
WALSIN	CHIP 0201 474P/6V3 \pm 10% X5R	0201X474K6R3	225.000	PCS
WALSIN	CHIP 0201 474P/6.3V M X5R	0201X474M6R3	135.000	PCS
WALSIN	CHIP 0603 474P/50V Z Y5V	0603F474Z500	588.000	PCS
WALSIN	CHIP 0805 475P/10V \pm 10% X5R	0805X475K100	495.000	PCS
WALSIN	CHIP 1206 475P/25V \pm 10% X5R	1206X475K250	190.000	PCS
WALSIN	CHIP 0805 475P/50V \pm 10% X5R	0805X475K500	108.000	PCS
WALSIN	CHIP 0603 475P/6.3V \pm 10% X5R	0603X475K6R3	124.000	PCS
WALSIN	CHIP 0402 475P/10V \pm 20% X5R	0402X475M100	550.000	PCS
WALSIN	CHIP 0805 475P/10V Z Y5V	0805F475Z100	348.000	PCS

WALSIN	CHIP 0805 475P/16V Z Y5V	0805F475Z160	423.000	PCS
WALSIN	CHIP 1206 475P/16V Z Y5V	1206F475Z160	201.000	PCS
WALSIN	CHIP 0603 476P/6.3V $\pm 20\%$ X5R	0603X476M6R3	112.000	PCS
WALSIN	CHIP 0805 476P/6.3V $\pm 20\%$ X5R	0805X476M6R3	177.000	PCS
WALSIN	CHIP 1206 476P/6.3V $\pm 20\%$ X5R	1206X476M6R3	118.000	PCS
WALSIN	RF 0201 4P/25V ± 0.1 PF NPO	RF03N4R0B250	540.000	PCS
WALSIN	CHIP 0402 4.3P/50V ± 0.25 PF NP	0402N4R3C500	140.000	PCS
WALSIN	CHIP 0201 4.7P/25V ± 0.1 PF NPO	0201N4R7B250	285.000	PCS
WALSIN	RF 0201 4.7P/25V ± 0.1 PF NPO	RF03N4R7B250	180.000	PCS
WALSIN	CHIP 0603 4.7P/50V ± 0.25 PF NP	0603N4R7C500	376.000	PCS
WALSIN	CHIP 0805 4.7P/50V ± 0.25 PF NP	0805N4R7C500	276.000	PCS
WALSIN	CHIP 0603 51P/50V $\pm 2\%$ NPO	0603N510G500	156.000	PCS
WALSIN	CHIP 0402 51P/50V $\pm 5\%$ NPO	0402N510J500	110.000	PCS
WALSIN	CHIP 0603 510P/50V $\pm 5\%$ NPO	0603N511J500	152.000	PCS
WALSIN	CHIP 0603 56P/50V $\pm 5\%$ NPO	0603N560J500	1.056.000	PCS
WALSIN	CHIP 0805 56P/50V $\pm 5\%$ NPO	0805N560J500	100.000	PCS
WALSIN	CHIP 0201 56P/50V $\pm 5\%$ NPO	0201N560J500	855.000	PCS
WALSIN	CHIP 0603 560P/50V $\pm 2\%$ NPO	0603N561G500	128.000	PCS
WALSIN	CHIP 0603 560P/50V $\pm 5\%$ NPO	0603N561J500	528.000	PCS
WALSIN	CHIP 0603 560P/50V $\pm 10\%$ X7R	0603B561K500	104.000	PCS
WALSIN	CHIP 0805 560P/50V $\pm 10\%$ X7R	0805B561K500	164.000	PCS
WALSIN	CHIP 0402 562P/25V $\pm 10\%$ X7R	0402B562K250	210.000	PCS
WALSIN	CHIP 0402 563P/25V $\pm 10\%$ X7R	0402B563K250	100.000	PCS
WALSIN	CHIP 1210 564P/50V $\pm 10\%$ X7R	1210B564K500	207.000	PCS
WALSIN	CHIP 0603 5P/50V ± 0.25 PF NPO	0603N5R0C500	280.000	PCS
WALSIN	CHIP 0402 5P/50V ± 0.25 PF NPO	0402N5R0C500	320.000	PCS
WALSIN	CHIP 0603 5.6P/50V ± 0.1 PF NPO	0603N5R6B500	100.000	PCS
WALSIN	CHIP 0603 5.6P/50V ± 0.25 PF NP	0603N5R6C500	124.000	PCS
WALSIN	CHIP 0402 5.6P/50V ± 0.25 PF NP	0402N5R6C500	750.000	PCS
WALSIN	CHIP 0603 5.6P/50V ± 0.5 PF NPO	0603N5R6D500	128.000	PCS
WALSIN	CHIP 0402 5.6P/50V ± 0.5 PF NPO	0402N5R6D500	170.000	PCS
WALSIN	CHIP 0201 5.6P/50V ± 0.5 PF NPO	0201N5R6D500	105.000	PCS
WALSIN	CHIP 0603 62P/50V $\pm 5\%$ NPO	0603N620J500	136.000	PCS
WALSIN	CHIP 0603 68P/50V $\pm 1\%$ NPO	0603N680F500	156.000	PCS
WALSIN	CHIP 0603 68P/100V $\pm 5\%$ NPO	0603N680J101	108.000	PCS
WALSIN	CHIP 0603 68P/250V $\pm 5\%$ NPO	0603N680J251	196.000	PCS
WALSIN	CHIP 0603 68P/50V $\pm 5\%$ NPO	0603N680J500	580.000	PCS
WALSIN	0603 680P/100V $\pm 5\%$ NPO 車用	MT18N681J101	160.000	PCS
WALSIN	CHIP 1206 680P/100V $\pm 5\%$ NPO	1206N681J101	272.000	PCS
WALSIN	CHIP 0603 680P/50V $\pm 5\%$ NPO	0603N681J500	2.836.000	PCS
WALSIN	CHIP 0201 680P/25V $\pm 10\%$ X7R	0201B681K250	300.000	PCS
WALSIN	CHIP 0805 682P/50V $\pm 5\%$ NPO	0805N682J500	234.000	PCS
WALSIN	CHIP 0603 682P/100V $\pm 10\%$ X7R	0603B682K101	120.000	PCS
WALSIN	CHIP 0603 682P/50V $\pm 10\%$ X7R	0603B682K500	1.316.000	PCS
WALSIN	CHIP 0402 682P/50V $\pm 10\%$ X7R	0402B682K500	110.000	PCS
WALSIN	CHIP 0603 6.2P/50V ± 0.25 PF NP	0603N6R2C500	320.000	PCS
WALSIN	RF 0402 6.8P/50V ± 0.1 PF NPO	RF15N6R8B500	100.000	PCS
WALSIN	CHIP 0201 6.8P/50V ± 0.25 PF NP	0201N6R8C500	120.000	PCS
WALSIN	CHIP 0603 6.8P/50V ± 0.5 PF NPO	0603N6R8D500	224.000	PCS
WALSIN	CHIP 1206 6.8P/50V ± 0.5 PF NPO	1206N6R8D500	104.000	PCS
WALSIN	CHIP 0402 6.8P/50V ± 0.5 PF NP	0402N6R8D500	320.000	PCS
WALSIN	CHIP 0603 75P/50V $\pm 2\%$ NPO	0603N750G500	148.000	PCS
WALSIN	CHIP 0603 7P/50V ± 0.25 PF NP	0603N7R0C500	260.000	PCS
WALSIN	CHIP 0402 7P/50V ± 0.25 PF NPO	0402N7R0C500	2.400.000	PCS
WALSIN	CHIP 0402 7P/50V ± 0.5 PF NPO	0402N7R0D500	670.000	PCS
WALSIN	CHIP 0603 7.5P/50V ± 0.25 PF NP	0603N7R5C500	120.000	PCS
WALSIN	CHIP 0402 82P/50V $\pm 1\%$ NPO	0402N820F500	130.000	PCS
WALSIN	CHIP 0603 82P/50V $\pm 2\%$ NPO	0603N820G500	112.000	PCS
WALSIN	CHIP 0805 82P/100V $\pm 5\%$ NPO	0805N820J101	104.000	PCS

WALSIN	CHIP 0603 82P/50V ±5% NPO	0603N820J500	380.000	PCS
WALSIN	CHIP 0402 82P/50V ±5% NPO	0402N820J500	330.000	PCS
WALSIN	CHIP 1206 820P/50V ±5% NPO	1206N821J500	176.000	PCS
WALSIN	CHIP 0402 820P/50V ±5% NPO	0402N821J500	370.000	PCS
WALSIN	CHIP 0603 820P/50V ±10% X7R	0603B821K500	664.000	PCS
WALSIN	CHIP 0402 820P/50V ±10% X7R	0402B821K500	1.080.000	PCS
WALSIN	CHIP 0402 822P/50V ±10% X7R	0402B822K500	450.000	PCS
WALSIN	CHIP 0603 8P/50V ±0.25PF NPO	0603N8R0C500	364.000	PCS
WALSIN	CHIP 0402 8P/50V ±0.5PF NPO	0402N8R0D500	290.000	PCS
WALSIN	CHIP 0402 8.2P/50V C NPO	0402N8R2C500	1.020.000	PCS
WALSIN	CHIP 0805 8.2P/50V ±0.5PF NPO	0805N8R2D500	124.000	PCS
WALSIN	CHIP 0201 8.2P/50V ±0.5PF NPO	0201N8R2D500	510.000	PCS
WALSIN	CHIP 0603 9P/50V ±0.25% NPO	0603N9R0C500	140.000	PCS
WALSIN	CHIP 0402 9P/50V ±0.5PF NPO	0402N9R0D500	130.000	PCS
SAMSUNG	CHIP 0603 0.3P/50V ±0.25PF NP	CL10C0R3CB8NNNC	140.000	PCS
SAMSUNG	CHIP 0603 0.5P/50V ±0.25PF NP	CL10C0R5CB8NNNC	196.000	PCS
SAMSUNG	CHIP 0402 10P/50V ±5% NPO	CL05C100JB5NNNC	1.400.000	PCS
SAMSUNG	CHIP 1206 100P/50V ±5% NPO	CL31C101JBCNNNC	412.000	PCS
SAMSUNG	CHIP 0402 100P/50V ±5% NPO	CL05C101JB5NNNC	1.100.000	PCS
SAMSUNG	0402 100P/50V ±5% NPO 車規	CL05C101JB51PNC	100.000	PCS
SAMSUNG	CHIP 0201 100P/50V ±5% NPO	CL03C101JB3NNNC	260.000	PCS
SAMSUNG	CHIP 0603 102P/50V ±5% X7R	CL10B102JB8NNNC	100.000	PCS
SAMSUNG	CHIP 0402 102P/50V ±5% X7R	CL05B102JB5NNNC	300.000	PCS
SAMSUNG	CHIP 0201 102P/16V ±10% X7R	CL03B102KO3NNNC	120.000	PCS
SAMSUNG	CHIP 0603 102P/50V ±10% X7R	CL10B102KB8NNNC	436.000	PCS
SAMSUNG	CHIP 0805 102P/50V ±10% X7R	CL21B102KBCNNNC	100.000	PCS
SAMSUNG	CHIP 1206 102P/50V ±10% X7R	CL31B102KBCNNNC	380.000	PCS
SAMSUNG	CHIP 0402 102P/50V ±10% X7R	CL05B102KB5NNNC	5.900.000	PCS
SAMSUNG	0402 102P/50V ±10% X7R 車規	CL05B102KB5VPNC	100.000	PCS
SAMSUNG	CHIP 0402 103P/16V ±5% X7R	CL05B103JO5NNNC	2.010.000	PCS
SAMSUNG	CHIP 0201 103P/10V ±10% X5R	CL03A103KP3NNNC	1.130.000	PCS
SAMSUNG	CHIP 0603 103P/16V ±10% X7R	CL10B103KO8NNNC	104.000	PCS
SAMSUNG	CHIP 0402 103P/16V ±10% X7R	CL05B103KO5NNNC	290.000	PCS
SAMSUNG	CHIP 0603 103P/50V ±10% X7R	CL10B103KB8NNNC	104.000	PCS
SAMSUNG	CHIP 0402 103P/50V ±10% X7R	CL05B103KB5NNNC	19.320.000	PCS
SAMSUNG	CHIP 0201 104P/10V ±10% X5R	CL03A104KP3NNNC	840.000	PCS
SAMSUNG	CHIP 0201 104P/10V K X5R 15K/R	CL03A104KP3NNNH	17.910.000	PCS
SAMSUNG	CHIP 0402 104P/10V ±10% X7R	CL05B104KP5NNNC	160.000	PCS
SAMSUNG	CHIP 0402 104P/16V ±10% X5R	CL05A104KO5NNNC	100.000	PCS
SAMSUNG	CHIP 0603 104P/16V ±10% X7R	CL10B104KO8NNNC	4.620.000	PCS
SAMSUNG	CHIP 0402 104P/16V ±10% X7R	CL05B104KO5NNNC	70.400.000	PCS
SAMSUNG	CHIP 0603 104P/25V ±10% X5R	CL10A104KA8NNNC	532.000	PCS
SAMSUNG	CHIP 0201 104P/25V ±10% X5R	CL03A104KA3NNNC	1.390.000	PCS
SAMSUNG	0402 104P/25V ±10% X7R 車規	CL05B104KA54PNC	100.000	PCS
SAMSUNG	CHIP 0603 104P/50V ±10% X7R	CL10B104KB8NNNC	4.420.000	PCS
SAMSUNG	0603 104P/50V ±10% X7R 車規	CL10B104KB8WPNC	15.212.000	PCS
SAMSUNG	CHIP 0805 104P/50V ±10% X7R	CL21B104KBCNNNC	2.856.000	PCS
SAMSUNG	0402 104P/50V ±10% X7R 車規	CL05B104KB54PNC	2.970.000	PCS
SAMSUNG	CHIP 0201 104P/6.3V ±10% X5R	CL03A104KQ3NNNC	3.630.000	PCS
SAMSUNG	CHIP 0402 104P/16V Z Y5V	CL05F104ZO5NNNC	720.000	PCS
SAMSUNG	CHIP 0603 104P/50V Z Y5V	CL10F104ZB8NNNC	976.000	PCS
SAMSUNG	CHIP 0805 104P/50V Z Y5V	CL21F104ZBCNNNC	300.000	PCS

SAMSUNG	CHIP 1206 105P/100V ±10% X7R	CL31B105KCHNNNE	128.000	PCS
SAMSUNG	CHIP 0402 105P/10V ±10% X5R	CL05A105KP5NNNC	46.850.000	PCS
SAMSUNG	CHIP 0201 105P/10V ±10% X5R	CL03A105KP3NSNC	400.000	PCS
SAMSUNG	CHIP 0603 105P/10V ±10% X7R	CL10B105KP8NNNC	556.000	PCS
SAMSUNG	CHIP 0603 105P/16V ±10% X5R	CL10A105KO8NNNC	17.060.000	PCS
SAMSUNG	CHIP 0805 105P/16V ±10% X5R	CL21A105KOFNNNE	1.030.000	PCS
SAMSUNG	CHIP 0402 105P/16V ±10% X5R	CL05A105KO5NNNC	5.380.000	PCS
SAMSUNG	CHIP 0603 105P/16V ±10% X7R	CL10B105KO8NNNC	132.000	PCS
SAMSUNG	CHIP 0805 105P/16V ±10% X7R	CL21B105KOFNNNE	120.000	PCS
SAMSUNG	CHIP 0805 105P/25V ±10% X7R	CL21B105KAFNNNE	600.000	PCS
SAMSUNG	CHIP 0603 105P/50V ±10% X5R	CL10A105KB8NNNC	692.000	PCS
SAMSUNG	CHIP 0201 105P/6.3V ±10% X5R	CL03A105KQ3CSNH	255.000	PCS
SAMSUNG	0201 105P/10V ±20% X5R 10K/R	CL03A105MP3NSNC	150.000	PCS
SAMSUNG	CHIP 0201 105P/16V ±20% X5R	CL03A105MO3NRNH	750.000	PCS
SAMSUNG	CHIP 0805 105P/50V M X7R	CL21B105MBFNNNE	1.906.000	PCS
SAMSUNG	CHIP 0201 105P/6.3V ±20% X5R	CL03A105MQ3CSNH	46.740.000	PCS
SAMSUNG	0201 105P/6.3V ±20% X5R 10K/R	CL03A105MQ3CSNC	6.000.000	PCS
SAMSUNG	CHIP 0603 106P/10V ±10% X5R	CL10A106KP8NNNC	13.156.000	PCS
SAMSUNG	CHIP 0805 106P/10V ±10% X5R	CL21A106KPFNNNE	5.182.000	PCS
SAMSUNG	CHIP 0805 106P/16V ±10% X5R	CL21A106KOQNNNE	26.120.000	PCS
SAMSUNG	CHIP 1210 106P/16V ±10% X5R	CL32A106KOJNNNE	335.000	PCS
SAMSUNG	CHIP 1206 106P/25V ±10% X5R	CL31A106KAHNNNE	3.480.000	PCS
SAMSUNG	CHIP 1210 106P/25V ±10% X5R	CL32A106KAJNNNE	490.000	PCS
SAMSUNG	CHIP 0805 106P/25V ±10% X6S	CL21X106KAYNNNE	618.000	PCS
SAMSUNG	CHIP 0603 106P/6V3 ±10% X5R	CL10A106KQ8NNNC	1.600.000	PCS
SAMSUNG	CHIP 0805 106P/6.3V ±10% X7R	CL21B106KQQNNNE	692.000	PCS
SAMSUNG	CHIP 0603 106P/10V ±20% X5R	CL10A106MP8NNNC	1.852.000	PCS
SAMSUNG	CHIP 0805 106P/10V ±20% X5R	CL21A106MPFNNNE	216.000	PCS
SAMSUNG	CHIP 0402 106P/10V ±20% X5R	CL05A106MP5NUNC	1.010.000	PCS
SAMSUNG	CHIP 0603 106P/16V ±20% X5R	CL10A106MO8NQNC	9.172.000	PCS
SAMSUNG	CHIP 1206 106P/16V ±20% X5R	CL31A106MOHNNNE	534.000	PCS
SAMSUNG	CHIP 0603 106P/4V ±20% X6S	CL10X106MR8NNNC	1.372.000	PCS
SAMSUNG	CHIP 0603 106P/6V3 ±20% X5R	CL10A106MQ8NNNC	27.782.000	PCS
SAMSUNG	CHIP 0402 106P/6V3 ±20% X5R	CL05A106MQ5NUNC	47.940.000	PCS
SAMSUNG	CHIP 0603 106P/6.3V ±20% X6S	CL10X106MQ8NNNC	120.000	PCS
SAMSUNG	CHIP 0805 106P/10V Z Y5V	CL21F106ZPFNNNE	116.000	PCS
SAMSUNG	CHIP 0603 12P/50V ±5% NPO	CL10C120JB8NNNC	156.000	PCS
SAMSUNG	CHIP 0805 12P/50V ±5% NPO	CL21C120JBANNNC	360.000	PCS
SAMSUNG	0402 12P/50V ±5% NPO 車規	CL05C120JB51PNC	100.000	PCS
SAMSUNG	CHIP 0603 122P/50V ±10% X7R	CL10B122KB8NNNC	488.000	PCS
SAMSUNG	0402 150P/50V ±5% NPO 車規	CL05C151JB51PNC	100.000	PCS
SAMSUNG	CHIP 0805 150P/50V ±10% X7R	CL21B151KBANNNC	180.000	PCS
SAMSUNG	CHIP 0805 152P/50V ±10% X7R	CL21B152KBANNNC	448.000	PCS
SAMSUNG	CHIP 0402 154P/10V ±10% X5R	CL05A154KP5NNNC	500.000	PCS
SAMSUNG	CHIP 0402 18P/50V ±5% NPO	CL05C180JB5NNNC	230.000	PCS
SAMSUNG	0402 18P/50V ±5% NPO 車規	CL05C180JB51PNC	100.000	PCS
SAMSUNG	CHIP 0603 180P/50V ±5% NPO	CL10C181JB8NNNC	1.080.000	PCS
SAMSUNG	CHIP 0805 180P/50V ±5% NPO	CL21C181JBANNNC	704.000	PCS
SAMSUNG	CHIP 0402 180P/50V ±5% NPO	CL05C181JB5NNNC	180.000	PCS
SAMSUNG	CHIP 0603 180P/50V ±10% X7R	CL10B181KB8NNNC	344.000	PCS

SAMSUNG	CHIP 0603 182P/50V ±10% X7R	CL10B182KB8NNNC	228.000	PCS
SAMSUNG	CHIP 0805 182P/50V ±10% X7R	CL21B182KBANNNC	448.000	PCS
SAMSUNG	CHIP 0402 182P/50V ±10% X7R	CL05B182KB5NNNC	160.000	PCS
SAMSUNG	CHIP 0603 1P/50V ±0.25PF NPO	CL10C010CB8NNNC	904.000	PCS
SAMSUNG	CHIP 0805 1P/50V ±0.25PF NPO	CL21C010CBANNNC	644.000	PCS
SAMSUNG	CHIP 0402 1P/50V ±0.25PF NPO	CL05C010CB5NNNC	200.000	PCS
SAMSUNG	CHIP 0603 1.2P/50V ±0.25PF NP	CL10C1R2CB8NNNC	324.000	PCS
SAMSUNG	CHIP 0805 1.2P/50V ±0.25PF NP	CL21C1R2CBANNNC	1.068.000	PCS
SAMSUNG	CHIP 0402 1.2P/50V ±0.25PF NP	CL05C1R2CB5NNNC	130.000	PCS
SAMSUNG	CHIP 0402 1.5P/50V ±0.1PF NPO	CL05C1R5BB5NNNC	4.210.000	PCS
SAMSUNG	CHIP 0603 1.5P/50V ±0.25PF NP	CL10C1R5CB8NNNC	428.000	PCS
SAMSUNG	CHIP 0805 1.5P/50V ±0.25PF NP	CL21C1R5CBANNNC	1.252.000	PCS
SAMSUNG	CHIP 0603 1.8P/50V ±0.25PF NP	CL10C1R8CB8NNNC	596.000	PCS
SAMSUNG	CHIP 0603 200P/50V ±10% X7R	CL10B201KB8NNNC	432.000	PCS
SAMSUNG	CHIP 0402 22P/50V ±5% NPO	CL05C220JB5NNNC	510.000	PCS
SAMSUNG	CHIP 0603 220P/50V ±10% X7R	CL10B221KB8NNNC	728.000	PCS
SAMSUNG	CHIP 0603 222P/50V ±10% X7R	CL10B222KB8NNNC	176.000	PCS
SAMSUNG	0402 222P/50V ±10% X7R 車規	CL05B222KB5VPNC	100.000	PCS
SAMSUNG	CHIP 0805 223P/50V ±10% X7R	CL21B223KBCNNNC	608.000	PCS
SAMSUNG	CHIP 0805 223P/50V ±10% X7R	CL21B223KBANNNC	132.000	PCS
SAMSUNG	CHIP 0402 223P/50V ±10% X7R	CL05B223KB5NNNC	190.000	PCS
SAMSUNG	CHIP 0402 224P/10V ±10% X5R	CL05A224KP5NNNC	1.880.000	PCS
SAMSUNG	CHIP 0402 224P/10V ±10% X7R	CL05B224KP5NNNC	2.070.000	PCS
SAMSUNG	CHIP 0805 224P/16V ±10% X7R	CL21B224KOFNNNE	158.000	PCS
SAMSUNG	CHIP 0805 224P/16V ±10% X7R	CL21B224KOCNNNC	1.436.000	PCS
SAMSUNG	CHIP 0402 224P/16V ±10% X7R	CL05B224KO5NNNC	5.920.000	PCS
SAMSUNG	CHIP 0603 224P/50V ±10% X5R	CL10A224KB8NNNC	1.680.000	PCS
SAMSUNG	0805 224P/50V ±10% X7R 車規	CL21B224KBFVPNE	170.000	PCS
SAMSUNG	CHIP 0402 224P/6.3V ±10% X5R	CL05A224KQ5NNNC	190.000	PCS
SAMSUNG	CHIP 0201 224P/6.3V ±10% X5R	CL03A224KQ3NNNC	920.000	PCS
SAMSUNG	CHIP 0201 224P/6V3 ±20% X5R	CL03A224MQ3NNNC	600.000	PCS
SAMSUNG	CHIP 0805 224P/50V Z Y5V	CL21F224ZBFNNNE	280.000	PCS
SAMSUNG	CHIP 0603 225P/10V ±10% X5R	CL10A225KP8NNNC	1.004.000	PCS
SAMSUNG	0603 225P/10V ±10% X7R 4K/REE	CL10B225KP8NNNC	816.000	PCS
SAMSUNG	CHIP 0805 225P/16V ±10% X5R	CL21A225KOFNNNE	2.182.000	PCS
SAMSUNG	CHIP 0402 225P/16V ±10% X5R	CL05A225KO5NQNC	800.000	PCS
SAMSUNG	CHIP 0603 225P/25V ±10% X5R	CL10A225KA8NNNC	564.000	PCS
SAMSUNG	CHIP 0805 225P/25V ±10% X7R	CL21B225KAFNNNE	165.000	PCS
SAMSUNG	CHIP 1206 225P/25V ±10% X7R	CL31B225KAHNNNE	840.000	PCS
SAMSUNG	CHIP 0603 225P/6.3V ±10% X5R	CL10A225KQ8NNNC	4.156.000	PCS
SAMSUNG	CHIP 0402 225P/6.3V ±10% X5R	CL05A225KQ5NSNC	620.000	PCS
SAMSUNG	CHIP 0603 225P/6V3 ±10% X7R	CL10B225KQ8NNNC	248.000	PCS
SAMSUNG	CHIP 0402 225P/10V ±20% X5R	CL05A225MP5NSNC	1.730.000	PCS
SAMSUNG	CHIP 0402 225P/6.3V ±20% X5R	CL05A225MQ5NNNC	3.320.000	PCS
SAMSUNG	CHIP 0402 225P/6.3V ±20% X5R	CL05A225MQ5NSNC	7.760.000	PCS
SAMSUNG	CHIP 0201 225P/6.3V ±20% X5R	CL03A225MQ3CRNC	730.000	PCS
SAMSUNG	CHIP 1206 226P/10V ±10% X5R	CL31A226KPHNNNE	1.402.000	PCS
SAMSUNG	0805 226P/16V ±10% X5R 2K/R	CL21A226KOQNNNE	714.000	PCS
SAMSUNG	CHIP 0603 226P/10V M X5R 3K/RE	CL10A226MP8NUNE	5.483.000	PCS

SAMSUNG	CHIP 1206 226P/16V ±20% X5R	CL31A226MOHNNNE	132.000	PCS
SAMSUNG	CHIP 0805 226P/25V ±20% X5R	CL21A226MAQNNNE	3.868.000	PCS
SAMSUNG	CHIP 0603 226P/4V ±20% X6S	CL10X226MR8NUNE	201.000	PCS
SAMSUNG	0603 226P/6.3V ±20% X5R 3K/R	CL10A226MQ8NRNE	3.798.000	PCS
SAMSUNG	CHIP 0805 226P/6.3V ±20% X5R	CL21A226MQQNNNE	55.366.000	PCS
SAMSUNG	CHIP 0402 226P/6.3V ±20% X5R	CL05A226MQ5QUNC	150.000	PCS
SAMSUNG	CHIP 1210 226P/6.3V ±20% X5R	CL32A226MQJNNNE	137.000	PCS
SAMSUNG	CHIP 0805 226P/6V3 ±20% X6S	CL21X226MQQNNNE	180.000	PCS
SAMSUNG	CHIP 1206 226P/10V Z Y5V	CL31F226ZPHNNNE	1.204.000	PCS
SAMSUNG	CHIP 0402 24P/50V ±5% NPO	CL05C240JB5NNNC	140.000	PCS
SAMSUNG	CHIP 0603 25P/50V ±5% NPO	CL10C250JB8NNNC	152.000	PCS
SAMSUNG	CHIP 0805 25P/50V ±5% NPO	CL21C250JBANNNC	108.000	PCS
SAMSUNG	CHIP 0805 27P/50V ±5% NPO	CL21C270JBANNNC	216.000	PCS
SAMSUNG	0402 27P/50V ±5% NPO 車規	CL05C270JB51PNC	100.000	PCS
SAMSUNG	CHIP 0805 270P/50V ±5% NPO	CL21C271JBANNNC	416.000	PCS
SAMSUNG	CHIP 0603 270P/50V ±10% X7R	CL10B271KB8NNNC	424.000	PCS
SAMSUNG	CHIP 0805 270P/50V ±10% X7R	CL21B271KBANNNC	540.000	PCS
SAMSUNG	CHIP 0402 272P/50V ±10% X7R	CL05B272KB5NNNC	200.000	PCS
SAMSUNG	CHIP 0805 2P/50V ±0.25PF NPO	CL21C020CBANNNC	192.000	PCS
SAMSUNG	CHIP 0402 2P/50V ±0.25PF NPO	CL05C020CB5NNNC	150.000	PCS
SAMSUNG	CHIP 0603 2.2P/50V ±0.25PF NP	CL10C2R2CB8NNNC	1.272.000	PCS
SAMSUNG	CHIP 0805 2.2P/50V ±0.25PF NP	CL21C2R2CBANNNC	124.000	PCS
SAMSUNG	CHIP 0603 2.7P/50V ±0.25PF NP	CL10C2R7CB8NNNC	260.000	PCS
SAMSUNG	CHIP 0805 2.7P/50V ±0.25PF NP	CL21C2R7CBANNNC	368.000	PCS
SAMSUNG	CHIP 0603 30P/50V ±5% NPO	CL10C300JB8NNNC	100.000	PCS
SAMSUNG	CHIP 0805 30P/50V ±5% NPO	CL21C300JBANNNC	108.000	PCS
SAMSUNG	CHIP 0402 30P/50V ±5% NPO	CL05C300JB5NNNC	180.000	PCS
SAMSUNG	0402 33P/50V ±5% NPO 車規	CL05C330JB51PNC	100.000	PCS
SAMSUNG	CHIP 0805 330P/50V ±10% X7R	CL21B331KBANNNC	548.000	PCS
SAMSUNG	CHIP 1206 332P/50V ±10% X7R	CL31B332KBCNNNC	108.000	PCS
SAMSUNG	CHIP 0402 333P/16V ±10% X7R	CL05B333KO5NNNC	750.000	PCS
SAMSUNG	CHIP 0805 333P/50V ±10% X7R	CL21B333KBANNNC	1.164.000	PCS
SAMSUNG	0402 333P/50V ±10% X7R 車規	CL05B333KB5VPNC	100.000	PCS
SAMSUNG	CHIP 0603 335P/10V ±10% X5R	CL10A335KP8NNNC	504.000	PCS
SAMSUNG	CHIP 0603 36P/50V ±5% NPO	CL10C360JB8NNNC	116.000	PCS
SAMSUNG	CHIP 0805 39P/50V ±5% NPO	CL21C390JBANNNC	660.000	PCS
SAMSUNG	CHIP 0603 390P/50V ±10% X7R	CL10B391KB8NNNC	148.000	PCS
SAMSUNG	CHIP 0805 390P/50V ±10% X7R	CL21B391KBANNNC	496.000	PCS
SAMSUNG	CHIP 0402 390P/50V ±10% X7R	CL05B391KB5NNNC	210.000	PCS
SAMSUNG	CHIP 0805 3P/50V ±0.25PF NPO	CL21C030CBANNNC	152.000	PCS
SAMSUNG	CHIP 0402 3P/50V ±0.25PF NPO	CL05C030CB5NNNC	2.570.000	PCS
SAMSUNG	CHIP 0805 3.3P/50V ±0.25PF NP	CL21C3R3CBANNNC	604.000	PCS
SAMSUNG	CHIP 0603 3.9P/50V ±0.25PF NP	CL10C3R9CB8NNNC	276.000	PCS
SAMSUNG	CHIP 0805 3.9P/50V ±0.25PF NP	CL21C3R9CBANNNC	516.000	PCS
SAMSUNG	CHIP 0402 47P/50V ±5% NPO	CL05C470JB5NNNC	416.000	PCS
SAMSUNG	CHIP 0603 470P/50V ±10% X7R	CL10B471KB8NNNC	116.000	PCS
SAMSUNG	CHIP 0402 470P/50V ±10% X7R	CL05B471KB5NNNC	310.000	PCS
SAMSUNG	0402 470P/50V ±10% X7R 車規	CL05B471KB5VPNC	100.000	PCS
SAMSUNG	0402 472P/50V ±10% X7R 車規	CL05B472KB5VPNC	100.000	PCS
SAMSUNG	CHIP 0402 473P/10V ±10% X5R	CL05A473KP5NNNC	5.870.000	PCS

SAMSUNG	CHIP 0402 473P/10V ±10% X7R	CL05B473KP5NNNC	6.400.000	PCS
SAMSUNG	CHIP 0402 474P/10V ±10% X5R	CL05A474KP5NNNC	230.000	PCS
SAMSUNG	CHIP 0805 474P/16V ±10% X7R	CL21B474KOFNNNE	668.000	PCS
SAMSUNG	CHIP 0402 474P/25V ±10% X5R	CL05A474KA5NNNC	970.000	PCS
SAMSUNG	CHIP 0201 474P/6.3V M X5R	CL03A474MQ3NNNH	555.000	PCS
SAMSUNG	CHIP 0805 474P/50V Z Y5V	CL21F474ZBFNNNE	1.020.000	PCS
SAMSUNG	CHIP 0603 475P/10V ±10% X5R	CL10A475KP8NNNC	5.024.000	PCS
SAMSUNG	CHIP 0805 475P/10V ±10% X5R	CL21A475KPFNNNE	1.802.000	PCS
SAMSUNG	CHIP 0402 475P/10V ±10% X5R	CL05A475KP5NRNC	580.000	PCS
SAMSUNG	CHIP 1206 475P/50V ±10% X7R	CL31B475KBHNNNE	578.000	PCS
SAMSUNG	CHIP 1210 475P/50V ±10% X7R	CL32B475KBJNNNE	117.000	PCS
SAMSUNG	CHIP 0603 475P/6.3V ±10% X5R	CL10A475KQ8NNNC	93.734.000	PCS
SAMSUNG	CHIP 0805 475P/6V3 ±10% X7R	CL21B475KQFNNNE	274.000	PCS
SAMSUNG	CHIP 0402 475P/10V ±20% X5R	CL05A475MP5NRNC	2.890.000	PCS
SAMSUNG	CHIP 0603 475P/6.3V ±20% X5R	CL10A475MQ8NNNC	480.000	PCS
SAMSUNG	CHIP 0402 475P/6.3V ±20% X5R	CL05A475MQ5NRNC	2.760.000	PCS
SAMSUNG	CHIP 0603 476P/6.3V ±20% X5R	CL10A476MQ8QRNC	268.000	PCS
SAMSUNG	CHIP 0805 4P/50V ±0.25PF NPO	CL21C040CBANNNC	112.000	PCS
SAMSUNG	CHIP 0603 4.7P/50V ±0.25PF NP	CL10C4R7CB8NNNC	436.000	PCS
SAMSUNG	CHIP 0805 4.7P/50V ±0.25PF NP	CL21C4R7CBANNNC	2.368.000	PCS
SAMSUNG	CHIP 0603 56P/50V ±5% NPO	CL10C560JB8NNNC	672.000	PCS
SAMSUNG	CHIP 0805 56P/50V ±5% NPO	CL21C560JBANNNC	404.000	PCS
SAMSUNG	CHIP 0805 560P/50V ±10% X7R	CL21B561KBANNNC	204.000	PCS
SAMSUNG	CHIP 0603 5P/50V ±0.25PF NPO	CL10C050CB8NNNC	564.000	PCS
SAMSUNG	CHIP 0603 5.1P/50V ±0.25PF NP	CL10C5R1CB8NNNC	484.000	PCS
SAMSUNG	CHIP 0603 5.6P/50V ±0.5PF NPO	CL10C5R6DB8NNNC	372.000	PCS
SAMSUNG	0402 68P/50V ±5% NPO 車規	CL05C680JB51PNC	100.000	PCS
SAMSUNG	0402 680P/50V ±10% X7R 車規	CL05B681KB5VPNC	100.000	PCS
SAMSUNG	0402 683P/16V ±10% X7R 車規	CL05B683KO5VPNC	100.000	PCS
SAMSUNG	CHIP 0402 684P/6V3 ±5% X6S	CL05X684JQ5NNNC	190.000	PCS
SAMSUNG	CHIP 0805 6.8P/50V ±0.5PF NPO	CL21C6R8DBANNNC	372.000	PCS
SAMSUNG	CHIP 0603 7P/50V ±0.25PF NP	CL10C070CB8NNNC	132.000	PCS
SAMSUNG	CHIP 0603 7P/50V ±0.5PF NPO	CL10C070DB8NNNC	120.000	PCS
SAMSUNG	CHIP 0805 7P/50V ±0.5PF NPO	CL21C070DBANNNC	580.000	PCS
SAMSUNG	CHIP 0603 7.5P/50V ±0.5PF NP	CL10C7R5DB8NNNC	208.000	PCS
SAMSUNG	0402 82P/100V ±5% NPO 車規	CL05C820JC51PNC	100.000	PCS
SAMSUNG	CHIP 0603 82P/50V ±5% NPO	CL10C820JB8NNNC	380.000	PCS
SAMSUNG	0402 82P/50V ±5% NPO 車規	CL05C820JB51PNC	100.000	PCS
SAMSUNG	CHIP 0603 820P/50V ±10% X7R	CL10B821KB8NNNC	136.000	PCS
SAMSUNG	CHIP 0603 8.2P/50V ±0.5PF NPO	CL10C8R2DB8NNNC	2.128.000	PCS
SAMSUNG	CHIP 0805 8.2P/50V ±0.5PF NPO	CL21C8R2DBANNNC	1.696.000	PCS
SAMSUNG	CHIP 0603 9P/50V ±0.25PF NPO	CL10C090CB8NNNC	204.000	PCS